
0/90 WOVEN ROVING (PLAIN WEAVE)

0/90 WOVEN ROVING (PLAIN WEAVE)



0/90 WOVEN ROVING (PLAIN WEAVE)

0/45 MOVEN ROVING





Fig 18 woven roving lay-up structure






Fig. 1D Stichbonded Biaxil




Fig. 1E Stichbonded Bi-Axial




Fig. 1F Stichbonded Bi-Axial




Fig. 1G Stichbonded Bi-Axial







Fig. 1H Stichbonded Bi-Axail







The 3rd Step: Compression Molding Process





Fig. 3H

Fig. 3I

Fig. 3J



2002. 10. 15

Fig.3K is a picture showing finished toe cap

BEST AVAILABLE COPY

Prepreg Machine




Fig 4A

SMC-R Machine




Fig 4B

BEST AVAILABLE COPY